


IFR 1200 Backlight



Sometimes the shop can be dark or weird light reflection coming onto the analog meters. Opened the IFR and looked around where a good place would be for additional lightning. Found a perfect hole which will hold a 3mm LED. Applied hot glue around LED and inserted it into the board. Let it try up and don't burn your fingers while holding HIHI Add resistors to LED's, add heat shrink, wires and connect it to the power supply board. LED's used are warm white.

